







Turbine Meter Head Loss Curves



Typical Head Loss Curves 2"-10" (Without Strainer)



Turbine Meter Head Loss Curves



Typical Head Loss Curves 2"- 8"

(With AWWA Strainer)

